

Comprehensive Inspections, Inc.

7866 Kingsview Lane N, Maple Grove, Minnesota 55311
Tel: 763-607-6350 Fax: 763-416-4234 Mobile: 763-607-6350
d.kratoska@comcast.net

SUMMARY REPORT

Client: David Foy
Realtor: Kevin Anderson, Counselor Realty
Inspection Address: 7866 Kingsview Lane N, Maple Grove, Minnesota 55311
Inspection Date: 2/22/2007 Start: 09:00 AM End: 12:30 AM
Inspected by: David J. Kratoska

We have identified various items on the subject structure that either require service or a second opinion now or require periodic maintenance in the normal course of home ownership. This is only a summary report and is intended as a guide to be used in both short and long term scheduling of maintenance items. Please read the complete report carefully as additional information and details are contained therein. It is always advisable to use experienced tradespeople or a qualified handyperson when contracting for work that may not be within the scope of your capabilities.

This report is the exclusive property of the Comprehensive Inspections, Inc. and the client whose name appears herewith, and its use by any unauthorized persons is prohibited.

Components and Conditions Needing Service

Structural

Various Hard Surfaces

Smoke detectors

- There are missing smoke detectors in the home - replacement warranted. Additionally, the inspector recommends the addition of U.L. approved carbon monoxide detectors on all levels of the home for added safety.

Fireplace

Gas fireplace

-

The basement gas fireplace supply was turned off - verification of operation prior to close is advised.

Exterior

Site & Other Observations

Landscaping Observations

- A tree limb is threatening the roof eaves, and should be removed before it further damages the roof eaves.
- Vegetation is encroaching on the structure, and should be kept a minimum of twelve inches away for the general welfare of the walls and foundation. Additionally there are areas of ground sloping toward the structure. Re grading is suggested.

Grading & Drainage

Moisture & Related Issues

- There are areas of direct earth contact with the siding material. All siding should have a minimum of 3 inch clear from the earth to prevent moisture damage.

Grade

- There are areas of negative grade. All grading should slope away from the home to help prevent water intrusion.

Exterior Components

Exterior Wooden Doors

- The front exterior door is a hollow-core type, which would not provide the security or insulation value of a solid-core type. Replacement should be considered.

Roof

Composition Shingle Roof

Gutters & Drainage

- Some downspouts are not properly discharged away from the home. Modifications advised.

Electrical

Main Panel

Circuit Breakers

- There are double lugged breakers in the panel. These breakers are designed to serve only one wire. The services of a qualified electrician would be in order.

GFIC

- There is a defective GFIC in the basement bathroom. Repair or replacement is warranted.

Kitchen

Kitchen

Valves & Connectors

- There is a leak on the hot-water connector at the faucet. Repairs warranted.

Stairs

Main Stairs

Handrails & Guardrails

- There are no handrail on the stairs. Handrails are an essential safety feature that should be added..

Laundry

Laundry Room

Valves & Connectors

- The water supply to washing machines is commonly left on, and the rubber hoses that are commonly used to supply water can become stressed and burst. For this reason we recommend replacing all rubber supply hoses with metal-braided ones that have a higher burst ratio.

Inspection Address: 7866 Kingsview Lane N, Maple Grove, Minnesota 55311
Inspection Date/Time: 2/22/2007 09:00 AM to 12:30 AM

Dryer Vent

- Replacement of the plastic exhaust vent with metal is advised. The plastic vents can dry out, get brittle and crack allowing unwanted moisture in the home and possible carbon monoxide poisoning.

Garage

Double-Car Garage

Garage Side Door

- The base of the garage side door is moisture damaged and delaminating, and should be repaired or replaced..

Automatic Opener

- The infra red auto-reversing sensor mechanisms are functional but located higher than the recommend six inches above grade. Modifications advised.

Comprehensive Inspections, Inc.

7866 Kingsview Lane N, Maple Grove, Minnesota 55311
Tel: 763-607-6350 Fax: 763-416-4234 Mobile: 763-607-6350
d.kratoska@comcast.net

CONFIDENTIAL INSPECTION REPORT

PREPARED FOR:

David Foy

INSPECTION ADDRESS

7866 Kingsview Lane N, Maple Grove, Minnesota 55311

INSPECTION DATE

2/22/2007 09:00 AM to 12:30 AM

REPRESENTED BY:

Kevin Anderson
Counselor Realty



This report is the exclusive property of the Comprehensive Inspections, Inc. and the client whose name appears herewith, and its use by any unauthorized persons is prohibited.

GENERAL INFORMATION

Inspection Address: 7866 Kingsview Lane N, Maple Grove, Minnesota 55311
Inspection Date: 2/22/2007 Time: 09:00 AM to 12:30 AM
Weather: Clear and Dry - Temperature at time of inspection: 30 degrees

Inspected by: David J. Kratoska

Client Information: David Foy
7866 Kingsview Lane N, Maple Grove, Minnesota 55311
Phone: 763-420-7080
Mobile: 612-990-5200

Buyer's Agent: Counselor Realty
Kevin Anderson
13601 - 80th Circle N, Maple Grove, Minnesota 55369
Phone: 763-438-3609
Mobile: 6129905200

Seller's Agent: Edina Realty
John Udderman
2407 109th Ave., Suite # 100, Blaine, MN 55449
Phone: 763-795-1902

Structure Type: Wood Frame
Furnished: Yes
Number of Stories: One

Structure Style: Split Entry

Structure Orientation: North

Estimated Year Built: 1987
Unofficial Sq.Ft.: 3400

People on Site At Time of Inspection: Buyer(s)
Buyer's Agent

PLEASE NOTE:

This report is the exclusive property of Comprehensive Home Inspections, Inc. and the client whose name appears herewith, and its use by any unauthorized persons is strictly prohibited.

The observations and opinions expressed within this report are those of Comprehensive Home Inspections, Inc. and supercede any alleged verbal comments. We inspect all of the systems, components, and conditions described in accordance with the standards of practice of the National Association of Home Inspectors (NAHI), and those that we do not inspect are clearly disclaimed in the contract and/or in the aforementioned standards.

In accordance with the terms of the contract, the service recommendations that we make in this report should be completed well before the close of escrow by licensed specialists, who may well identify additional defects or recommend some upgrades that could affect your evaluation of the property.

Report File: ! 07-02-23 David Foy Group (SAMPLE)

SCOPE OF WORK

You have contracted with Comprehensive Inspections Inc. to perform a generalist inspection in accordance with the standards of practice established by NAHI, a copy of which is available upon request. Generalist inspections are essentially visual, and distinct from those of specialists, inasmuch as they do not include the use of specialized instruments, the dismantling of equipment, or the sampling of air and inert materials. Consequently, a generalist inspection and the subsequent report will not be as comprehensive, nor as technically exhaustive, as that generated by specialists, and it is not intended to be. The purpose of a generalist inspection is to identify significant defects or adverse conditions that would warrant a specialist evaluation. Therefore, you should be aware of the limitations of this type of inspection, which are clearly indicated in the standards. However, the inspection is not intended to document the type of cosmetic deficiencies that would be apparent to the average person, and certainly not intended to identify insignificant deficiencies. Similarly, we do not inspect for vermin infestation, which is the responsibility of a licensed exterminator.

Most homes built after 1978, are generally assumed to be free of asbestos and many other common environmental contaminants. However, as a courtesy to our clients, we are including some well documented, and therefore public, information about several environmental contaminants that could be of concern to you and your family, all of which we do not have the expertise or the authority to evaluate, such as asbestos, radon, methane, formaldehyde, termites and other wood-destroying organisms, pests and rodents, molds, microbes, bacterial organisms, and electromagnetic radiation, to name some of the more commonplace ones. Nevertheless, we will attempt to alert you to any suspicious substances that would warrant evaluation by a specialist. However, health and safety, and environmental hygiene are deeply personal responsibilities, and you should make sure that you are familiar with any contaminant that could affect your home environment. You can learn more about contaminants that can affect your home from a booklet published by The Environmental Protection Agency, which you can read online at www.epa.gov/iaq/pubs/insidest.htm.

Mold is one such contaminant. It is a microorganism that has tiny seeds, or spores, that are spread on the air, land, and feed on organic matter. It has been in existence throughout human history, and actually contributes to the life process. It takes many different forms, many of them benign, like mildew. Some characterized as allergens are relatively benign but can provoke allergic reactions among sensitive people, and others characterized as pathogens can have adverse health effects on large segments of the population, such as the very young, the elderly, and people with suppressed immune systems. However, there are less common molds that are called toxigens that represent a serious health threat. All molds flourish in the presence of moisture, and we make a concerted effort to look for any evidence of it wherever there could be a water source, including that from condensation. Interestingly, the molds that commonly appear on ceramic tiles in bathrooms do not usually constitute a health threat, but they should be removed. However, some visibly similar molds that form on cellulose materials, such as on drywall, plaster, and wood, are potentially toxigenic. If mold is to be found anywhere within a home, it will likely be in the area of tubs, showers, toilets, sinks, water heaters, evaporator coils, inside attics with unvented bathroom exhaust fans, and return-air compartments that draw outside air, all of which are areas that we inspect very conscientiously. Nevertheless, mold can appear as though spontaneously at any time, so you should be prepared to monitor your home, and particularly those areas that we identified. Naturally, it is equally important to maintain clean air-supply ducts and to change filters as soon as they become soiled, because contaminated ducts are a common breeding ground for dust mites, rust, and other contaminants. Regardless, although some mold-like substances may be visually identified, the specific identification of molds can only be determined by specialists and laboratory analysis, and is absolutely beyond the scope of our inspection. Nonetheless, as a prudent investment in environmental hygiene, we categorically recommend that you have your home tested for the presence of any such contaminants, and particularly if you or any member of your family suffers from allergies or asthma. Also, you can learn more about mold from an Environmental Protection Agency document entitled "A Brief Guide to Mold, Moisture and Your Home," by visiting their web site at: <http://www.epa.gov/iaq/molds/moldguide.html>, from which it can be downloaded.

Asbestos is a notorious contaminant that could be present in any home built before 1978. It is a naturally occurring mineral fiber that was first used by the Greek and Romans in the first century, and it has been widely used throughout the modern world in a variety of thermal insulators, including those in the form of paper wraps, bats, blocks, and blankets. However, it can also be found in a wide variety of other products too numerous to mention, including duct insulation and acoustical materials, plasters, siding, floor tiles, heat vents, and roofing products. Although perhaps recognized as being present in some documented forms, asbestos can only be

specifically identified by laboratory analysis. The most common asbestos fiber that exists in residential products is chrysotile, which belongs to the serpentine or white-asbestos group, and was used in the clutches and brake shoes of automobiles for many years. However, a single asbestos fiber is said to be able to cause cancer, and is therefore a potential health threat and a litigious issue. Significantly, asbestos fibers are only dangerous when they are released into the air and inhaled, and for this reason authorities such as the Environmental Protection Agency [EPA] and the Consumer Product Safety Commission [CPSC] distinguish between asbestos that is in good condition, or non-friable, and that which is in poor condition, or friable, which means that its fibers could be easily crumbled and become airborne. However, we are not specialists and, regardless of the condition of any real or suspected asbestos-containing material [ACM], we would not endorse it and recommend having it evaluated by a specialist.

Radon is a gas that results from the natural decay of radioactive materials within the soil, and is purported to be the second leading cause of lung cancer in the United States. The gas is able to enter homes through the voids around pipes in concrete floors or through the floorboards of poorly ventilated crawlspaces, and particularly when the ground is wet and the gas cannot easily escape through the soil and be dispersed into the atmosphere. However, it cannot be detected by the senses, and its existence can only be determined by sophisticated instruments and laboratory analysis, which is completely beyond the scope of our service. However, you can learn more about radon and other environmental contaminants and their affects on health, by contacting the Environmental Protection Agency (EPA), at www.epa.gov/radon/images/hmbuygud.pdf, and it would be prudent for you to enquire about any high radon readings that might be prevalent in the general area surrounding your home.

Lead poses an equally serious health threat. In the 1920's, it was commonly found in many plumbing systems. In fact, the word "plumbing" is derived from the Latin word "plumbum," which means lead. When in use as a component of a waste system, it does not constitute a viable health threat, but as a component of potable water pipes it would certainly be a health-hazard. Although rarely found in use, lead could be present in any home build as recently as the nineteen forties. For instance, lead was an active ingredient in many household paints, which can be released in the process of sanding, and even be ingested by small children and animals chewing on painted surfaces. Fortunately, the lead in painted surfaces can be detected by industrial hygienists using sophisticated instruments, but testing for it is not cheap. There are other environmental contaminants, some of which we have already mentioned, and others that may be relatively benign. However, we are not environmental hygienists, and as we stated earlier we disclaim any responsibility for testing or establishing the presence of any environmental contaminant, and recommend that you schedule whatever specialist inspections that may deem prudent before the close of escrow.

Structural

All structures are dependent on the soil beneath them for support, but soils are not uniform. Some that might appear to be firm and solid can liquefy and become unstable during seismic activity. Also, there are soils that can expand to twice their volume with the influx of water and move structures with relative ease, raising and lowering them and fracturing slabs and other hard surfaces. In fact, expansive soils have accounted for more structural damage than most natural disasters. Regardless, foundations are not uniform, and conform to the structural standard of the year in which they were built. In accordance with our standards of practice, we identify foundation types and look for any evidence of structural deficiencies. However, cracks or deteriorated surfaces in foundations are quite common. In fact, it would be rare to find a raised foundation wall that was not cracked or deteriorated in some way, or a slab foundation that did not include some cracks concealed beneath the carpeting and padding. Fortunately, most of these cracks are related to the curing process or to common settling, including some wide ones called cold-joint separations that typically contour the footings, but others can be more structurally significant and reveal the presence of expansive soils that can predicate more or less continual movement. We will certainly alert you to any suspicious cracks if they are clearly visible. However, we are not specialists, and in the absence of any major defects we may not recommend that you consult with a foundation contractor, a structural engineer, or a geologist, but this should not deter you from seeking the opinion of any such expert.

Various Hard Surfaces

Common Observations

Informational Conditions

There are common settling, or curing, cracks in the hard surfaces. This is somewhat predictable, and is typically not regarded as being structurally significant, but we are not specialists and you may wish to have this confirmed by one.

Smoke detectors

Components and Conditions Needing Service

There are missing smoke detectors in the home - replacement warranted. Additionally, the inspector recommends the addition of U.L. approved carbon monoxide detectors on all levels of the home for added safety.

Radon results

Informational Conditions

No radon sampling was performed in this structure.

Structural Elements

Identification of Wall Structure

Informational Conditions

The walls are conventionally framed with wooden studs.

Identification of Floor Structure

Informational Conditions

Floor truss system.

Identification of Ceiling Structure

Informational Conditions

Drywall covering

Identification of Roof Structure

Informational Conditions

The roof structure consists of a prefabricated truss system.

Basement

General Comments

Informational Conditions

This residence has a basement foundation. Such foundations permit access, and provide a convenient area for the distribution of water pipes, drain pipes, vent pipes, electrical conduits, and ducts. However, although basement foundations are far from uniform, most include concrete footings and walls that extend above the ground with anchor bolts that hold the house onto the foundation, but the size and spacing of the bolts vary. In the absence of major defects, most structural engineers agree that the one critical issue with basement foundations is that they should be bolted. Our inspection of these foundations conforms to industry standards, which is that of a generalist and not a specialist, and we do not use any specialized instruments to establish that the structure is level. We typically enter all accessible areas, to confirm that foundations are bolted and to look for any evidence of structural deformation or damage, but we may not comment on minor deficiencies, such as on commonplace settling cracks in the stem walls and slight deviations from plumb and level in the intermediate floor framing, which would have little structural significance. Interestingly, there is no absolute standard for evaluating cracks, but those that are less than ¼" and which do not exhibit any vertical or horizontal displacement are generally not regarded as being structurally relevant. Nevertheless, all others should be evaluated by a specialist. However, in the absence of any major defects, we may not recommend that you consult with a foundation contractor, a structural engineer, or a geologist, but this should not deter you from seeking the opinion of any such expert.

Basement Foundation Type

Informational Conditions

The foundation is built over a basement and should meet commonly accepted standards.

Method of Evaluation

Informational Conditions

We evaluated the basement foundation by accessing and evaluating the components within.

Basement Observations

Informational Conditions

The basement is accessible and in acceptable condition.

Structural Framing

Informational Conditions

The intermediate floor framing is in acceptable condition. There may be some deviations from plumb, level, etc, but none that would have any serious structural significance.

Poured Concrete Walls

Informational Conditions

The basement walls appear to be functional.

Electrical

Informational Conditions

The visible portions of the wiring in the basement are functional.

Stairs

Informational Conditions

We have evaluated the stairs and landing, and found them to be in acceptable condition.

Windows

General condition

Informational Conditions

The basement windows appear to be functional and operate as designed

Window latches and locks

Informational Conditions

The window latches appear to be in functional condition.

Fireplace

Gas fireplace

Components and Conditions Needing Service

The basement gas fireplace supply was turned off - verification of operation prior to close is advised.

Exterior

With the exception of townhomes, condominiums, and residences that are part of a planned urban development, or PUD, we evaluate the following exterior features: driveways, walkways, fences, gates, handrails, guardrails, yard walls, carports, patio covers, decks, building walls, fascia and trim, balconies, doors, windows, lights, and outlets. However, we do not evaluate any detached structures, such as storage sheds and stables, and we do not water test or evaluate subterranean drainage systems or any mechanical or remotely controlled components, such as driveway gates. Also, we do not evaluate landscape components, such as trees, shrubs, fountains, ponds, statuary, pottery, fire pits, patio fans, heat lamps, and decorative or low-voltage lighting. In addition, we do not comment on coatings or cosmetic deficiencies and the wear and tear associated with the passage of time, which would be apparent to the average person. However, cracks in hard surfaces can imply the presence of expansive soils that can result in continuous movement, but this could only be confirmed by a geological evaluation of the soil.

Site & Other Observations

Landscaping Observations

Components and Conditions Needing Service

A tree limb is threatening the roof eaves, and should be removed before it further damages the roof eaves. Vegetation is encroaching on the structure, and should be kept a minimum of twelve inches away for the general welfare of the walls and foundation. Additionally there are areas of ground sloping toward the structure. Re grading is suggested.

Grading & Drainage

Moisture & Related Issues

Components and Conditions Needing Service

There are areas of direct earth contact with the siding material. All siding should have a minimum of 3 inch clear from the earth to prevent moisture damage.

Sump Pumps

Informational Conditions

The drainage system includes a sump pump, which must be kept clean and monitored periodically or drainage problems could result.

Grade

Components and Conditions Needing Service

There are areas of negative grade. All grading should slope away from the home to help prevent water intrusion.

Inspection Address:
Inspection Date/Time:

7866 Kingsview Lane N, Maple Grove, Minnesota 55311
2/22/2007 09:00 AM to 12:30 AM

House Wall Finish

House Wall Finish Type

Informational Conditions

The house walls are finished with cement fiber board siding.

House Wall Finish Observations

Informational Conditions

The house wall finish is in acceptable condition.

Exterior Components

General Comments

Informational Conditions

It is important to maintain a property, including painting or sealing walkways, decks, and other hard surfaces, and it is particularly important to keep the house walls sealed, which provide the only barrier against deterioration. Unsealed cracks around windows, doors, and thresholds can permit moisture intrusion, which is the principle cause of the deterioration of any surface. Unfortunately, the evidence of such intrusion may only be obvious when it is raining. We have discovered leaking windows while it was raining that may not have been apparent otherwise. Regardless, there are many styles of windows but only two basic types, single and dual-glazed. Dual-glazed windows are superior, because they provide a thermal as well as an acoustical barrier. However, the hermetic seals on these windows can fail at any time, and cause condensation to form between the panes. Unfortunately, this is not always apparent, which is why we disclaim an evaluation of hermetic seals. Nevertheless, in accordance with industry standards, we test a representative number of unobstructed windows, and ensure that at least one window in every bedroom is operable and facilitates an emergency exit.

Driveways

Informational Conditions

The driveway is in acceptable condition. (asphalt)

Walkways

Informational Conditions

A walkway has been displaced by root movement and could present a trip-hazard.

Fascia & Trim

Informational Conditions

The fascia board and trim are in acceptable condition.

Sliding Glass Doors

Other Conditions

A panel in the dual-glazed slider has a broken hermetic seal, and may need to be replaced.

Exterior Wooden Doors

Components and Conditions Needing Service

The front exterior door is a hollow-core type, which would not provide the security or insulation value of a solid-core type. Replacement should be considered.

Steps & Handrails

Informational Conditions

The steps are in acceptable condition.

Guardrails

Informational Conditions

The guardrail, or guardrails, is an adequate height and in acceptable condition. However, standards for guardrails are not uniform. Nonetheless, common safety standards require them to be a minimum of forty-two inches high when the standing surface is thirty inches or more above grade. Also, guardrail pickets should be no more than four inches apart for child safety.

Screens

Informational Conditions

The window screens are functional.

Outlets

Informational Conditions

The outlets that were tested are functional and include ground-fault protection.

Lights

Informational Conditions

The lights outside the doors of the residence are functional. However, we do not inspect or evaluate decorative lights.

Caulking

Informational Conditions

The caulking appears to be in functional condition.

Deck

Informational Conditions

The deck cover material is in satisfactory condition.

Roof

There are many different roof types, which we evaluate by walking on their surfaces. If we are unable or unwilling to do this for any reason, we will indicate the method that was used to evaluate them. Every roof will wear differently relative to its age, the number of its layers, the quality of its material, the method of its application, its exposure to direct sunlight or other prevalent weather conditions, and the regularity of its maintenance. Regardless of its design-life, every roof is only as good as the waterproof membrane beneath it, which is concealed and cannot be examined without removing the roof material, and this is equally true of almost all roofs. In fact, the material on the majority of pitched roofs is not designed to be waterproof only water-resistant. However, what remains true of all roofs is that, whereas their condition can be evaluated, it is virtually impossible for anyone to detect a leak except as it is occurring or by specific water tests, which are beyond the scope of our service. Even water stains on ceilings, or on the framing within attics, could be old and will not necessarily confirm an active leak without some corroborative evidence, and such evidence can be deliberately concealed. Consequently, only the installers can credibly guarantee that a roof will not leak, and they do. We evaluate every roof conscientiously, and even attempt to approximate its age, but we will not predict its remaining life expectancy, or guarantee that it will not leak. Naturally, the sellers or the occupants of a residence will generally have the most intimate knowledge of the roof and of its history. Therefore, we recommend that you ask the sellers about it, and that you either include comprehensive roof coverage in your home insurance policy, or that you obtain a roof certification from an established local roofing company.

Composition Shingle Roof

General Comments

Informational Conditions

There are a wide variety of composition shingle roofs, which are comprised of asphalt or fiberglass materials impregnated with mineral granules that are designed to deflect the deteriorating ultra-violet rays of the sun. The commonest of these roofs are warranted by manufacturers to last from twenty to twenty-five years, and are typically guaranteed against leaks by the installer for three to five years. The actual life of the roof will vary, depending on a number of interrelated factors besides the quality of the material and the method of installation. However, the first indication of significant wear is apparent when the granules begin to separate and leave pockmarks or dark spots. This is referred to as primary decomposition, which means that the roof is in decline, and therefore susceptible to leakage. This typically begins with the hip and ridge shingles and to the field shingles on the south facing side. This does not mean that the roof needs to be replaced, but that it should be monitored more regularly and serviced when necessary. Regular maintenance will certainly extend the life of any roof, and will usually avert most leaks that only become evident after they have caused other damage.

Method of Evaluation

Informational Conditions

We evaluated the roof and its components by walking on its surface.

Estimated Age

Informational Conditions

The roof appears to be relatively new, and is not original. However, this is just an estimate and you should request the installation permit from the sellers, which will reveal its exact age and any warranty or guarantee that might be applicable.

Roofing Material

Informational Conditions

The roof is in acceptable condition at the time of the inspection.

Layered Material

Informational Conditions

The roof appears to be on layer.

Flashings

Informational Conditions

The roof flashings are in acceptable condition.

Skylights

Informational Conditions

The skylight appears to be in functional condition.

Gutters & Drainage

Functional Components and Conditions

The gutters appear to be in acceptable condition. However, without water in them it is difficult to judge whether they are correctly pitched to direct water into the downspouts, but they should function as they were intended.

Components and Conditions Needing Service

Some downspouts are not properly discharged away from the home. Modifications advised.

Plumbing

Plumbing systems have common components, but they are not uniform. In addition to fixtures, these components include gas pipes, water pipes, pressure regulators, pressure relief valves, shut-off valves, drain and vent pipes, and water-heating devices, some of which we do not test if they are not in daily use. The best and most dependable water pipes are copper, because they are not subject to the build-up of minerals that bond within galvanized pipes, and gradually restrict their inner diameter and reduce water volume. Water softeners can remove most of these minerals, but not once they are bonded within the pipes, for which there would be no remedy other than a re-pipe. The water pressure within pipes is commonly confused with water volume, but whereas high water volume is good high water pressure is not. In fact, whenever the street pressure exceeds eighty pounds per square inch a regulator is recommended, which typically comes factory preset between forty-five and sixty-five pounds per square inch. However, regardless of the pressure, leaks will occur in any system, and particularly in one with older galvanized pipes, or one in which the regulator fails and high pressure begins to stress the washers and diaphragms within the various components.

Waste and drainpipes pipes are equally varied, and range from modern ABS ones [acrylonitrile butadiene styrene] to older ones made of cast-iron, galvanized steel, clay, and even a cardboard-like material that is coated with tar. The condition of these pipes is usually directly related to their age. Older ones are subject to damage through decay and root movement, whereas the more modern ABS ones are virtually impervious to damage, although some rare batches have been alleged to be defective. However, inasmuch as significant portions of drainpipes are concealed, we can only infer their condition by observing the draw at drains. Nonetheless, blockages will occur in the life of any system, but blockages in drainpipes, and particularly in main drainpipes, can be expensive to repair, and for this reason we recommend having them video-scanned. This could also confirm that the house is connected to the public sewer system, which is important because all private systems must be evaluated by specialists.

Potable Water Supply Pipes

Water Main Shut-off Location

Informational Conditions

The main water shut off is located at the meter in the utility room

Pressure Regulators

Informational Conditions

A functional pressure regulator is in place on the plumbing system.

Copper Water Pipes

Informational Conditions

The potable water pipes are made of copper and are in acceptable condition

General Gas Components

Gas Main Shut-Off Location

Informational Conditions

The main gas shut off is located in the utility room.

Gas Supply Pipes

Informational Conditions

The visible portions of the gas pipes appear to be in acceptable condition.

Gas Water Heaters

General Comments

Informational Conditions

There are a wide variety of residential water heaters that range in capacity. They can be expected to last at least as long as their warranty, or from ten to twelve years, but they will generally last longer. However, few of them last longer than fifteen or twenty years and many eventually leak. So it is always wise to have them installed over a drain pan plumbed to the exterior. Also, it is prudent to flush them annually to remove minerals that include the calcium chloride bi-product of many water softening systems. The water temperature should be set at a minimum of 110 degrees Fahrenheit to kill microbes and a maximum of 130 degrees to prevent scalding. Also, water heaters can be dangerous if they are not equipped with either a pressure/temperature relief valve and discharge pipe.

Age Capacity & Location

Informational Conditions

Hot water is provided by a 10 year old, 50 gallon, water heater that is located in the basement.

Common Observations

Informational Conditions

The water heater is functional but beyond its warranty period.

Water Shut-Off Valve & Connectors

Informational Conditions

The shut-off valve and water connectors are functional.

Gas Shut-Off Valve & Connector

Informational Conditions

The gas control valve and its connector at the water heater are functional.

Vent Pipe & Cap

Informational Conditions

The vent pipe is functional.

Relief Valve & Discharge Pipe

Functional Components and Conditions

The water heater is equipped with a mandated pressure-temperature relief valve.

Drain Valve

Informational Conditions

The drain valve is in place and presumed to be functional.

Irrigation or Sprinklers

Automatic Sprinklers

Informational Conditions

The sprinkler system has been winterized and is not in the scope of this inspection.

Waste & Drainage Systems

General Comments

Informational Conditions

We attempt to evaluate drain pipes by flushing every drain that has an active fixture while observing its draw and watching for blockages or slow drains, but this is not a conclusive test and only a video-scan of the main line would confirm its actual condition. However, you can be sure that blockages will occur, usually relative in severity to the age of the system, and will range from minor ones in the branch lines, or at the traps beneath sinks, tubs, and showers, to major blockages in the main line. The minor ones are easily cleared, either by chemical means or by removing and cleaning the traps. However, if tree roots grow into the main drain that connects the house to the public sewer, repairs could become expensive and might include replacing the entire main line. For these reasons, we recommend that you ask the sellers if they have ever experienced any drainage problems, or you may wish to have the main waste line video-scanned before the close of escrow. Failing this, you should obtain an insurance policy that covers blockages and damage to the main line. However, most policies only cover plumbing repairs within the house, or the cost of roofer service, most of which are relatively inexpensive.

Type of Material

Informational Conditions

The waste lines in this home are PVC

Drain Waste & Vent Pipes

Informational Conditions

Based on industry recommended water tests, the drainpipes are functional at this time. However, only a video-scan of the main drainpipe could confirm its actual condition. (PVC)

Water softener

Water softener

Informational Conditions

There is an active water softener - testing this system is however outside the scope of this inspection.

Electrical

There are a wide variety of electrical systems with an even greater variety of components, and any one particular system may not conform to current standards or provide the same degree of service and safety. What is most significant about electrical systems however is that the national electrical code [NEC] is not retroactive, and therefore many residential systems do not comply with the latest safety standards. Regardless, we are not electricians and in compliance with our standards of practice we only test a representative number of switches and outlets and do not perform load-calculations to determine if the supply meets the demand. However, in the interests of safety, we regard every electrical deficiency and recommended upgrade as a latent hazard that should be serviced as soon as possible, and that the entire system be evaluated and certified as safe by an electrician. Therefore, it is essential that any recommendations that we may make for service or upgrades should be completed before the close of escrow, because an electrician could reveal additional

deficiencies or recommend some upgrades for which we would disclaim any further responsibility. However, we typically recommend upgrading outlets to have ground fault protection, which is a relatively inexpensive but essential safety feature. These outlets are often referred to as GFCI's, or ground fault circuit interrupters and, generally speaking, have been required in specific locations for more than thirty years, beginning with swimming pools and exterior outlets in 1971, and the list has been added to ever since: bathrooms in 1975, garages in 1978, spas and hot tubs in 1981, hydro tubs, massage equipment, boat houses, kitchens, and unfinished basements in 1987, crawlspaces in 1990, wet bars in 1993, and all kitchen countertop outlets with the exception of refrigerator and freezer outlets since 1996. Similarly, AFCI's or arc fault circuit interrupters, represent the very latest in circuit breaker technology, and have been required in all bedroom circuits since 2002. However, inasmuch as arc faults cause thousands of electrical fires and hundreds of deaths each year, we categorically recommend installing them at every circuit as a prudent safety feature.

Main Panel

General Comments

Informational Conditions

National safety standards require electrical panels to be weatherproof, readily accessible, and have a minimum of thirty-six inches of clear space in front of them for service. Also, they should have a main disconnect, and each circuit within the panel should be clearly labeled. Industry standards only require us to test a representative number of accessible switches, receptacles, and light fixtures. However, we attempt to test every one that is unobstructed, but if a residence is furnished we will obviously not be able to test each one.

Service Entrance

Informational Conditions

The main conductor lines are underground, or part of a lateral service entrance. This is characteristic of modern electrical services but, inasmuch as the service lines are underground and cannot be seen, they are not evaluated as part of our service.

Panel Size & Location

Informational Conditions

The residence is served by a 150 amp, 220 volt panel, located inside the garage.

Main Panel Observations

Informational Conditions

The panel and its components have no visible deficiencies.

Panel Cover Observations

Informational Conditions

The interior panel cover is in acceptable condition.

Wiring Observations

Informational Conditions

The visible portions of the wiring has no visible deficiencies.

Circuit Breakers

Components and Conditions Needing Service

There are double lugged breakers in the panel. These breakers are designed to serve only one wire. The services of a qualified electrician would be in order.

Grounding

Informational Conditions

The panel appears to be properly grounded

Wiring type

Informational Conditions

The main service entrance is aluminum - the required oxigard grease is present.

The branch wiring in this structure are comprised of both copper and aluminum.

GFIC

Components and Conditions Needing Service

There is a defective GFIC in the basement bathroom. Repair or replacement is warranted.

Heat-A/C

The components of most heating and air-conditioning systems have a design-life ranging from ten to twenty years, but can fail prematurely with poor maintenance, which is why we apprise you of their age whenever possible. We test and evaluate them in accordance with the standards of practice, which means that we do not dismantle and inspect the concealed portions of evaporator and condensing coils, the heat exchanger, which is also known as the firebox, electronic air-cleaners, humidifiers, ducts and in-line duct-motors or dampers. We perform a conscientious evaluation of both systems, but we are not specialists. However, even the most modern heating systems can produce carbon monoxide, which in a sealed or poorly ventilated room can result in sickness, debilitating injury, and even death. Therefore, in accordance with the terms of our contract, it is essential that any recommendations that we make for service or a second opinion be scheduled before the close of escrow, because a specialist could reveal additional defects or recommend further upgrades that could affect your evaluation of the property, and our service does not include any form of warranty or guarantee.

HVAC Split Systems

Age & Location

Informational Conditions

Central heat and air-conditioning are provided by a single split-system, consisting of a 20 year-old furnace with an evaporator coil that is located in basement , and a 10 ? year-old condensing coil that is located in side yard.

Common Observations

Informational Conditions

We did not test the air-conditioning system because the ambient temperature is too low. The manufacturer recommends that these units not be turned on below 60 degrees as damage may result.

Furnace

Informational Conditions

The furnace is functional.

Vent Pipe

Informational Conditions

The vent pipe has no visible deficiencies.

Circulating Fan

Informational Conditions

The circulating fan is clean and functional.

Gas Valve & Connector

Informational Conditions

The gas valve and connector are in acceptable condition.

Combustion-Air Vents

Informational Conditions

The combustion-air vents appear to be adequate to support complete combustion.

Condensate Drainpipe

Informational Conditions

The condensate drainpipe discharges correctly.

Condensing Coil Disconnect

Informational Conditions

The electrical disconnect at the condensing coil is functional.

Refrigerant Lines

Informational Conditions

The refrigerant lines are in acceptable condition.

Differential Temperature Readings

Informational Conditions

Not checked due to out door temperature being to low.

Thermostats

Informational Conditions

The thermostat is functional.

Registers

Informational Conditions

The registers are reasonably clean and functional.

Humidifier

Informational Conditions

In accordance with industry standards, we do not evaluate humidifiers as part of our service. However, because warm moisture can promote the growth of bacteria, yeasts, and molds, their reservoirs must be kept clean when in use, and desalinated and serviced when they are not in use.

Chimney

The Chimney Safety Institute of America has published industry standards for the inspection of chimneys, and on January 13, 2000, the National Fire Protection Association adopted these standards as code, known as NFPA 211. Our inspection of masonry and factory-built chimneys to what is known as a Level-One inspection, which is purely visual and not to be confused with Level-Two, and Level-Three inspections, which are performed by qualified specialists with a knowledge of codes and standards, and typically involves dismantling components and/or investigations with video-scan equipment and other means to evaluate chimneys.

Living Room Chimney

General Lined Masonry

Informational Conditions

The chimney is a lined masonry type, which is the most dependable because the flue liner not only provides a smooth transition for the bi-products of combustion to be vented beyond the residence but provides an approved thermal barrier as well. However, we recommend a level-two inspection by a qualified specialist within the contingency period or before the close of escrow, as recommended by NAPA standards "upon the sale or transfer of a property."

Weather Cap-Spark Arrestor

Informational Conditions

The chimney has a functional weather cap/spark arrestor.

Crown or Termination Cap

Informational Conditions

The crown, which is designed to seal the chimney wall and to shed rainwater and thereby prevent moisture from deteriorating the chimney, is in acceptable condition.

Chimney Flashings

Informational Conditions

The chimney flashings are in acceptable condition.

Chimney Flue

Informational Conditions

The portions of the flue that are visible appear to be in acceptable condition.

Fireplace

Informational Conditions

The fireplace is in acceptable condition.

Damper

Informational Conditions

The damper is functional.

Glass Doors

Informational Conditions

The fireplace glass doors are functional.

Hearth

Informational Conditions

The hearth is in acceptable condition.

Mantle

Informational Conditions

The mantle has cosmetic damage that you may wish to view for yourself.

Living

Our inspection of living space includes the visually accessible areas of walls, floors, cabinets and closets, and includes the testing of a representative number of windows and doors, switches and outlets. However, we do not evaluate window treatments, or move furniture, lift carpets or rugs, empty closets or cabinets, and we do not comment on cosmetic deficiencies. We may not comment on the cracks that appear around windows and doors, or which follow the lines of framing members and the seams of drywall and plasterboard. These cracks are a consequence of movement, such as wood shrinkage, common settling, and seismic activity, and will often reappear if they are not correctly repaired. Such cracks can become the subject of disputes, and are therefore best evaluated by a specialist. Similarly, there are a number of environmental pollutants that we have already elaborated upon, the specific identification of which is beyond the scope of our service but which can become equally contentious. In addition, there are a host of lesser contaminants, such as that from moisture penetrating carpet-covered cracks in floor slabs, as well as odors from household pets and cigarette smoke that can permeate walls, carpets, heating and air conditioning ducts, and other porous surfaces, and which can be difficult to eradicate. However, inasmuch as the sense of smell adjusts rapidly, and the sensitivity to such odors is certainly not uniform, we recommend that you make this determination for yourself, and particularly if you or any member of your family suffers from allergies or asthma, and then schedule whatever remedial services may be deemed necessary before the close of escrow.

Indoor Environmental Issues

Environmental Observations

Informational Conditions

We do not test for mold or measure indoor air quality, which the Consumer Product safety Commission ranks fifth among potential contaminants. Regardless, a person's health is a truly personal responsibility, and inasmuch as we do not inspect for mold or test for other environmental contaminants we recommend that you schedule an inspection by an environmental hygienist before the close of escrow. And this would be imperative if you or any member of your family suffers from allergies or asthma, and could require the sanitizing of air ducts and other concealed areas.

Note: Mold cannot exist without moisture. Therefore, any moisture whatsoever, whether it be from inadequate grading and drainage, a leaking roof, window, or door, or moisture from a faulty exhaust vent, a condensate pipe, an evaporator coil, or a component of a plumbing system should be serviced immediately, or the potential for mold infestation will remain.

Main Entry

No Recommended Service

Informational Conditions

We have evaluated the entry, and found it to be in acceptable condition.

Living Room

No Recommended Service

Informational Conditions

We have evaluated the living room, and found it to be in acceptable condition.

Dining Room

No Recommended Service

Informational Conditions

We have evaluated the dining room, and found it to be in acceptable condition.

Bedrooms

In accordance with the standards of practice, our inspection of bedrooms includes the visually accessible areas of walls, floors, cabinets and closets, and includes the testing of a representative number of windows and doors, switches and outlets. We evaluate windows to ensure that they meet light and ventilation requirements and facilitate an emergency exit or egress, but we do not evaluate window treatments, nor move furniture, lift carpets or rugs, empty closets or cabinets, and we do not comment on common cosmetic deficiencies.

Main Bedroom

No Recommended Service

Informational Conditions

We have evaluated the bedrooms, and found them to be in acceptable condition.

Doors

Informational Conditions

The doors are functional.

Flooring

Informational Conditions

The floor has no significant defects.

Walls & Ceiling

Informational Conditions

The walls and ceiling are in acceptable condition.

Dual-Glazed Windows

Informational Conditions

The windows that were unobstructed were checked, and found to be functional.

Closets

Functional Components and Conditions

The closet and its components are functional.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets that were unobstructed and able to be tested are functional.

Smoke Detector

Informational Conditions

The smoke detector is functional, but should be checked periodically.

Bathrooms

In accordance with industry standards, we do not comment on common cosmetic deficiencies, and do not evaluate window treatments, steam showers, and saunas. More importantly, we do not leak-test shower pans, which is usually the responsibility of a termite inspector. However, because of the possibility of water damage, most termite inspectors will not leak-test second floor shower pans without the written consent of the owners or occupants.

Powder Room

Size and Location

Informational Conditions

The powder room is located off the kitchen.

Doors

Functional Components and Conditions

The door is functional.

Flooring

Informational Conditions

The floor has no significant defects.

Walls & Ceiling

Informational Conditions

The walls and ceiling are in acceptable condition.

Cabinets

Functional Components and Conditions

The cabinets are in acceptable condition.

Sink Countertop

Functional Components and Conditions

The sink countertop is functional.

Sink Faucet Valves & Connectors Trap & Drain

Functional Components and Conditions

The sink and its components are functional.

Toilet

Functional Components and Conditions

The toilet is functional.

Exhaust Fan

Functional Components and Conditions

The exhaust fan is functional.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets are functional and include ground-fault protection.

Main Bathroom

Size and Location

Informational Conditions

The main bathroom is located on the upper level off the hallway.

No Recommended Service

Informational Conditions

We have evaluated the main bathroom, and found it to be in acceptable condition.

Doors

Functional Components and Conditions

The door is functional.

Flooring

Informational Conditions

The floor has no significant defects.

Walls & Ceiling

Informational Conditions

The walls and ceiling are in acceptable condition.

Dual-Glazed Windows

Functional Components and Conditions

The window is functional.

Cabinets

Functional Components and Conditions

The cabinets are in acceptable condition.

Sink Countertop

Functional Components and Conditions

The sink countertop is functional.

Sink Faucet Valves & Connectors Trap & Drain

Functional Components and Conditions

The sink and its components are functional.

Tub-Shower

Functional Components and Conditions

The tub/shower is functional.

Toilet & Bidet

Functional Components and Conditions

The toilet is functional.

Exhaust Fan

Functional Components and Conditions

The exhaust fan is functional.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets are functional and include ground-fault protection.

Kitchen

We test kitchen appliances for their functionality, and cannot evaluate them for their performance nor for the variety of their settings or cycles. However, if they are older than ten years, they may well exhibit decreased efficiency. Also, many older gas and electric ranges are not secured and can be easily tipped, particularly when any weight is applied to an open range door, and all such appliances should be confirmed to be secure. Regardless, we do not inspect the following items: free-standing appliances, refrigerators, trash-compactors, built-in toasters, coffee-makers, can-openers, blenders, instant hot-water dispensers, water-purifiers, barbecues, grills or rotisseries, timers, clocks, thermostats, the self-cleaning capability of ovens, and concealed or countertop lighting, which is convenient but often installed after the initial construction and not wired to national electrical standards.

Inspection Address:
Inspection Date/Time:

7866 Kingsview Lane N, Maple Grove, Minnesota 55311
2/22/2007 09:00 AM to 12:30 AM

Kitchen

Doors

Informational Conditions

The doors are functional.

Flooring

Informational Conditions

The floor has no significant defects. (carpeted)

Walls & Ceiling

Functional Components and Conditions

The walls and ceiling are in acceptable condition.

Dual-Glazed Windows

Functional Components and Conditions

The windows are functional.

Sink & Countertop

Informational Conditions

The counter top has typical cosmetic damage, which would not necessarily need to be serviced.

Cabinets

Informational Conditions

The cabinets have typical, cosmetic damage, or that which is commensurate with their age.

Valves & Connectors

Components and Conditions Needing Service

There is a leak on the hot-water connector at the faucet. Repairs warranted.

Faucet

Functional Components and Conditions

The sink faucet is functional.

Trap and Drain

Functional Components and Conditions

The trap and drain are functional.

Garbage Disposal

Functional Components and Conditions

The garbage disposal is functional.

Gas Range

Functional Components and Conditions

The gas range is functional, but was neither calibrated nor tested for its performance.

Dishwasher

Functional Components and Conditions

The dishwasher is functional.

Exhaust Fan or Downdraft

Informational Conditions

The exhaust fan is functional and a type that vents internally.

Built-in Microwave

Functional Components and Conditions

The built-in microwave is functional but we did not test it for leakage, which would require a specialized instrument.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets that were tested are functional and include ground-fault protection.

Refrigerator

Informational Conditions

The refrigerator appears to be in satisfactory condition
There is an active ice maker in the freezer.
Note: Testing ice makers and water dispensers are outside the scope of this inspection.

Hallway

Our evaluation of hallways is identical to that of living space, except that we pay particular attention to safety issues, such as those involving handrails, guardrails, and smoke detectors.

Primary Hallway

No Recommended Service

Informational Conditions

We have evaluated the hallway, and found it to be in acceptable condition.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets that were tested are functional.

Smoke Detector

Informational Conditions

The smoke detector is functional, but should be checked periodically.

Stairs

Our evaluation of staircases is identical to that of living space, except that we pay particular attention to safety issues, such as those involving handrails, guardrails, and smoke detectors.

Main Stairs

No Recommended Service

Informational Conditions

We have evaluated the stairs and landing, and found them to be in acceptable condition.

Handrails & Guardrails

Components and Conditions Needing Service

There are no handrail on the stairs. Handrails are an essential safety feature that should be added..

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets that were tested are functional.

Smoke Detector

Informational Conditions

The smoke detector is functional, but should be checked periodically.

Laundry

In accordance with industry standards, we do not test clothes dryers, nor washing machines and their water connections and drainpipes. However, there are two things that you should be aware of. The water supply to washing machines is usually left on, and their hoses can leak or burst under pressure and continue to flow. Therefore, we recommend replacing the rubber hose type with newer braided stainless steel ones that are much more dependable. You should also be aware that the newer washing machines discharge a greater volume of water than many of the older drainpipes can handle, which causes the water to back up and overflow, and the only remedy would be to replace the standpipe and trap with one that is a size larger.

Laundry Room

Doors

Functional Components and Conditions

The door is functional.

Flooring

Informational Conditions

The floor has no significant defects.

Walls & Ceiling

Informational Conditions

The walls and ceiling are in acceptable condition.

Dual-Glazed Windows

Functional Components and Conditions

The windows are functional.

Cabinets

Functional Components and Conditions

The cabinets are functional.

Closets

Functional Components and Conditions

The closet, or closets, are functional.

Exhaust Fan

Functional Components and Conditions

The exhaust fan is functional.

Sink

Functional Components and Conditions

The laundry sink is functional, and does not need service at this time.

Faucet

Functional Components and Conditions

The laundry sink faucet is functional.

Valves & Connectors

Functional Components and Conditions

The valves and connectors are functional. However, because they are not in daily use they typically become stiff or frozen.

Components and Conditions Needing Service

The water supply to washing machines is commonly left on, and the rubber hoses that are commonly used to supply water can become stressed and burst. For this reason we recommend replacing all rubber supply hoses with metal-braided ones that have a higher burst ratio.

Trap & Drain

Functional Components and Conditions

The trap and drain are functional.

Gas Valve & Connector

Informational Conditions

The gas valve and connector are functional.

Dryer Vent

Components and Conditions Needing Service

Replacement of the plastic exhaust vent with metal is advised. The plastic vents can dry out, get brittle and crack allowing unwanted moisture in the home and possible carbon monoxide poisoning.

Lights

Functional Components and Conditions

The lights are functional.

Outlets

Functional Components and Conditions

The outlets that were tested are functional.

Garage

It is not uncommon for moisture to penetrate garages, because their slabs are on-grade. Evidence of this is typically apparent in the form of efflorescence, or salt crystal formations, that result when moisture penetrates the concrete slab or sidewalls. This is a common with garages that are below grade, and some sidewalls are even cored to relieve the pressure that can build up behind them, and which actually promotes drainage through the garage. Also, if there is living space above the garage, that space will be seismically vulnerable. Ideally, the columns and beams around the garage door will be made of structural steel, but in many residences these components are made of wood but could include some structural accessories, such as post-straps and hold-downs, and plywood shear paneling. However, we are not an authority in such matters, and you may wish to discuss this further with a structural engineer. In addition, and inasmuch as garage door openings are not standard, you may wish to measure the opening to ensure that there is sufficient clearance to accommodate your vehicles.

Double-Car Garage

No Recommended Service

Informational Conditions

We have evaluated the garage, and found it to be in acceptable condition.

Slab Floor

Functional Components and Conditions

The slab floor is in acceptable condition. Small cracks are common and result as a consequence of the curing process, seismic activity, common settling, or the presence expansive soils, but are not structurally threatening. Also, you may notice some salt crystal formations that are activated by moisture penetrating the slab.

Informational Conditions

The slab floor is cracked, but not load-bearing. Such cracks are common and result as a consequence of the curing process, seismic activity, ordinary settling, or the presence of expansive soils, but are not structurally threatening.

Walls & Ceiling

Informational Conditions

The walls are sheathed and in acceptable condition.

Firewall Separation

Functional Components and Conditions

The firewall separating the garage from the residence is functional.

Entry Door Into the House

Functional Components and Conditions

The house entry door is solid core, or fire-rated, and self-closes in conformance with fire-safety regulations.

Garage Side Door

Components and Conditions Needing Service

The base of the garage side door is moisture damaged and delaminating, and should be repaired or replaced..

Garage Door & Hardware

Functional Components and Conditions

The garage door and its hardware are functional.

Automatic Opener

Functional Components and Conditions

The garage door opener is functional.

Components and Conditions Needing Service

The infra red auto-reversing sensor mechanisms are functional but located higher than the recommend six inches above grade. Modifications advised.

Lights

Functional Components and Conditions

The lights are functional, and do not need service at this time.

Attic

In accordance with our standards, we do not attempt to enter attics that have less than thirty-six inches of headroom, are restricted by ducts, or in which the insulation obscures the joists and thereby makes mobility hazardous, in which case we would inspect them as best we can from the access point. In regard to evaluating the type and amount of insulation on the attic floor, we use only generic terms and approximate measurements, and do not sample or test the material for specific identification. Also, we do not disturb or move any portion of it, and it may well obscure water pipes, electrical conduits, junction boxes, exhaust fans, and other components.

Primary Attic

Attic Access Location

Informational Conditions

The attic can be accessed through a hatch in the hallway ceiling.

Method of Evaluation

Informational Conditions

We evaluated the attic by direct access.

Framing

Informational Conditions

The roof framing consists of a factor- built truss system, comprised of components called chords, webs, and struts that are connected by wood or metal gussets nailed or glued in place. Each component of the truss is designed for a specific purpose, and cannot be removed or modified without compromising the integrity of the entire truss. The lowest component, which is called the chord and to which the ceiling is attached, can move by thermal expansion and contraction and cause creaking sounds, which are more pronounced in the mornings and evenings along with temperature changes. Such movement has no structural significance, but can result in small cracks or divots in the drywall or plaster.

Ventilation

Informational Conditions

Ventilation is provided by a combination of eave, dormer, turbine, or gable vents, and should be adequate.

Electrical

Informational Conditions

The electrical components that are fully visible appear to be in acceptable condition.

Blown-In Cellulose Insulation

Informational Conditions

The attic is adequately insulated, but not necessarily to a maximum standard. The amount of insulation can range from three to eighteen inches, depending upon the climate, the region, and the year in which the residence was constructed.

AFFILIATIONS AND CERTIFICATIONS



ICBO Certified Building Inspector # _____
ICBO Certified Mechanical Inspector # _____
ICBO Certified Combination Dwelling Inspector # _____
IAPMO Certified Mechanical Inspector # _____
California Real Estate Inspection Association "C.P.I." # _____
Structural Pest Inspector License # _____
AHERA Certified Building Inspector # _____

Inspector

REPORT CONCLUSION

7866 Kingsview Lane N, Maple Grove, Minnesota 55311

Congratulations on the purchase of your new home. Inasmuch as we never know who will be occupying or visiting a property, whether it be children or the elderly, we ask you to consider following these general safety recommendations: install smoke and carbon monoxide detectors; identify all escape and rescue ports; rehearse an emergency evacuation of the home; upgrade older electrical systems by at least adding ground-fault outlets; never service any electrical equipment without first disconnecting its power source; safety-film all non-tempered glass; ensure that every elevated window and the railings of stairs, landings, balconies, and decks are child-safe, meaning that barriers are in place or that the distance between the rails is not wider than three inches; regulate the temperature of water heaters to prevent scalding; make sure that goods that contain caustic or poisonous compounds, such as bleach, drain cleaners, and nail polish removers be stored where small children cannot reach them; ensure that all garage doors are well balanced and have a safety device, particularly if they are the heavy wooden type; remove any double-cylinder deadbolts from exterior doors; and consider installing child-safe locks and alarms on the exterior doors of all pool and spa properties.

We are proud of our service, and trust that you will be happy with the quality of our report. We have made every effort to provide you with an accurate assessment of the condition of the property and its components and to alert you to any significant defects or adverse conditions. However, we may not have tested every outlet, and opened every window and door, or identified every minor defect. Also because we are not specialists or because our inspection is essentially visual, latent defects could exist. Therefore, you should not regard our inspection as conferring a guarantee or warranty. It does not. It is simply a report on the general condition of a particular property at a given point in time. Furthermore, as a homeowner, you should expect problems to occur. Roofs will leak, drain lines will become blocked, and components and systems will fail without warning. For these reasons, you should take into consideration the age of the house and its components and keep a comprehensive insurance policy current. If you have been provided with a home protection policy, read it carefully. Such policies usually only cover insignificant costs, such as that of roofer service, and the representatives of some insurance companies can be expected to deny coverage on the grounds that a given condition was preexisting or not covered because of what they claim to be a code violation or a manufacture's defect. Therefore, you should read such policies very carefully, and depend upon our company for any consultation that you may need.

Thank you for taking the time to read this report, and call us if you have any questions or observations whatsoever. We are always attempting to improve the quality of our service and our report, and we will continue to adhere to the highest standards of the real estate industry and to treat everyone with kindness, courtesy, and respect.

TABLE OF CONTENTS

CONFIDENTIAL INSPECTION REPORT	1
GENERAL INFORMATION	2
SCOPE OF WORK	3
Structural	5
Various Hard Surfaces	5
Structural Elements	5
Basement	6
Windows	6
Fireplace	7
Exterior	7
Site & Other Observations	7
Grading & Drainage	7
House Wall Finish	8
Exterior Components	8
Roof	9
Composition Shingle Roof	9
Plumbing	10
Potable Water Supply Pipes	11
General Gas Components	11
Gas Water Heaters	11
Irrigation or Sprinklers	12
Waste & Drainage Systems	12
Water softener	12
Electrical	12
Main Panel	13
Heat-A/C	14
HVAC Split Systems	14
Chimney	15
Living Room Chimney	15
Living	16
Indoor Environmental Issues	16
Main Entry	16
Living Room	17
Dining Room	17
Bedrooms	17
Main Bedroom	17
Bathrooms	18
Powder Room	18
Main Bathroom	18
Kitchen	19
Kitchen	20
Hallway	21
Primary Hallway	21
Stairs	21
Main Stairs	21
Laundry	22
Laundry Room	22
Garage	23
Double-Car Garage	23
Attic	24

Inspection Address: 7866 Kingsview Lane N, Maple Grove, Minnesota 55311
Inspection Date/Time: 2/22/2007 09:00 AM to 12:30 AM

Primary Attic	24
Certifications and Affiliations	25
Report Conclusion	26